Certified Unified Program Agency County of Riverside Community Health Services Agency Department of Environmental Health Hazardous Materials Management Division HAZARDOUS WASTE GENERATOR INSPECTION SUPPLEMENTAL REPORT

Facility Name: B.F. Goodrich (Generator)

Facility# 80679

Date of Inspection: Initial-9/21-25/2001; Follow-up dates October 2001 through March 2002

Report By: Sandra J. Facinelli, Hazardous Materials Management Specialist

A full facility inspection was conducted of the above facility throughout several days during the above time period. All buildings/structures on site were inspected as well as a complete perimeter walk. See Attachments I and II for a facility map and a list of buildings, operations and the hazardous wastes being generated at the time of inspection.

The following is a list of the violations that were documented at the time of inspection. These violations are marked on Page 1. (Note: These are the items that were stated verbally to you during the inspections and they were also listed in the field notes that you were given a copy of during our follow-up discussions.) Please provide a written response indicating that the violations have been corrected as soon as possible.

103B.) In Building #1 there was a satellite accumulation area with 2 separate bins, one for 'Alodine' waste and one for miscellaneous waste, the labels on the outside of the container were transposed and the 'Alodine' waste was labeled as miscellaneous and vice versa. The bags inside the bins were not labeled. In Building #4 there was a small lab waste container under the sink in an old laboratory room that was not labeled. In Building #5 there was a 1-gal, waste hexane container that was not labeled in the laboratory sink. Outside near the 'Co-Gen' area, there were several containers with unknown contents that were not labeled. Outside of Building #59 a 55-gal drum containing used oil was not labeled. In Building #60 there were boxes of CRTs that were improperly labeled as non-hazardous waste instead of the proper 'Universal Waste' label. The Generator shall ensure hazardous waste is placed in appropriate and properly labeled accumulation areas and that all hazardons wastes and universal wastes are properly labeled as to contents.

103F.) In Building #5 the 1-gal, waste hexane container was open. Outside of Building #59 a 55-gal. drum containing used oil was open. The Generator shall ensure all hazardous wastes are properly closed unless adding to or removing from contents.

105D.) At the time of initial inspection, there were no specific written procedures for hazardous waste spills available on site for on-site hazardous waste clean-up contractor employees. The Generator shall ensure a written contingency plan, including emergency response procedures for different types of hazardous waste spills, is available on site.

Behind Building #5 the lab sink, process wastewater and rinsewater, and corrosive liquid waste from the 'hand-line', all drain to an underground single-walled tank in an un-lined concrete vault which connects to underground single-wall steel piping that runs to an aboveground tank. The contents of this tank are then pumped and recycled on-site in the wastewater treatment plant. The Generator does not consider this an aboveground hazardous waste tank because the liquid in the tank is recycled on site in their process. Near Building #27 there was a concrete containment area containing several inches of built-up corrosive residue open to the environment. Outside of Building #59, there was an oil spill on the ground near the drums in the containment area. Several buildings on site, including Building #17, Building #24, Building #29 and Building #65, have aboveground bazardous waste 'totes' containing 'Alodine' (chromebased substance) wastewater, waste fixer containing silver, oily water from steam-cleaning, etc. Many of these totes containing hazardous wastes have single-walled piping in below-grade unlined trenches that are not able to be visually inspected. The Generator considers these totes as portable tanks, not subject to aboveground hazardous waste tank requirements;

Certified Unified Program Agency County of Riverside Community Health Services Agency Department of Environmental Health Hazardous Materials Management Division HAZARDOUS WASTE GENERATOR INSPECTION SUPPLEMENTAL REPORT

Facility Name: B.F. Goodrich (Generator)

Page 3 of 3

Facility# 80679

Date of Inspection: Initial-9/21-25/2001; Follow-up dates October 2001 through March 2002 Report By: Sandra J. Facinelli, Hazardous Materials Management Specialist

106.) cont. however, there is no method for detection or containment of a hazardous waste release from these single-walled lines. Also, according to facility records, there are old underground tank structures on site which formerly contained Alodine waste which may require remediation. The Generator shall maintain all hazardous wastes to minimize the possibility of release and ensure hazardous wastes have not been released into the environment. The Generator shall assess the alternatives of lining below-grade trenches, visually inspecting lines, upgrading lines with double-wall piping, or some other method to maintain these lines to minimize the possibility of release.

114.) Respirator fit testing records for on-site hazardous waste contractor employees were not updated at the time of inspection. An employee in Building #4, working in the chrome-based paint area, was not wearing gloves. Training for use of personal protective equipment is required to be updated annually for employees dealing with hazardous waste. The training program shall include specific hazardous waste training for all employees.

NO OTHER VIOLATIONS WERE NOTED AT THE TIME OF INSPECTION. THE GENERATOR SHALL SUBMIT A CERTIFICATION OF COMPLIANCE WITH THE ABOVE ITEMS.

Department of Environmental Health Hazardous Materials Management Division HAZARDOUS WASTE GENERATOR INSPECTION ATTACHMENT I

Facility Name: B.F. Goodrich (Generator)

List of Buildings, Operations and Hazardous Wastes
Facility# 80679

Attachment I Page 1 of 3

Date of Inspection: Initial- 9/21-25/2001; Follow-up dates October 2001 through March 2002

Report By: Sandra J. Facinelli, Hazardous Materials Management Specialist

Location	Operations	Hazardous Wastes
Building #1	Gridlock- machining aluminum, lay-up and assembly	Coolam, cutting fluids, rags and wipers
	Chromated conversion coating	Alodine waste (chrome and water), rags and wipers
	Paint crib	Gun-wash, filters, cups, stirrers, rags, wipers, paint, primer and miscellaneous waste
	Painting areas and spray booths	Adhesive primer, debris, brushes, coveralls, mask, filters, gloves, paint sludge, cardboard
	Grinding operations	Excluded recyclable material, abrasive blasting grit (Aluminum oxide)
	Shipping	
Building #2	Empty offices	
Building #3	Operations Support and Tooling	Rags, debris, paint waste and miscellaneous
Building #4	Bond shop and Adhesive operations	Waste pre-preg, liquid adhesive, catalyst, mixing cups, potting tubes, stirrers, solvent, coveralls, gloves, rags, resins
	Perchloroethylene degreasing system	Still bottoms, contaminated condensate, activated carbon, liquid perc.
	Clean Line Anodizing Process Line and surface prep and Old 'C-Line'	NaOH, nitric acid, phosphoric acid, trace metals, wastewater, ion exchange cylinders
	Laboratory	General lab waste, flammable liquids, corrosives, sink waste, rags, debris, adhesive waste
	Spray and bake adhesive and primer coating	Gun-wash, filters, cups, stirrers, rags, wipers, paint, primer and miscellaneous waste
	Chromated conversion coating	Alodine waste, rags and wipers
Bond Shop Annex- Building #1 and #4	Post Bond- De-flashing, route and flash	Miscellaneous wastes, rags, wipers, Alodine waste
	Spray booths	Gun-wash, filters, cups, stirrers, rags, wipers, paint, primer, debris, paint booth waste
	Machining/clean-up	Miscellaneous rag and solvent waste
	Adhesive Crib	Waste pre-preg, liquid adhesive, catalyst,

Facility Name: B.F. Goodrich (Generator)

List of Buildings, Operations and Hazardous Wastes
Facility# 80679

Attachment I (cont.) Page 2 of 3

Date of Inspection: Initial- 9/21-25/2001; Follow-up dates October 2001 through March 2002

Report By: Sandra J. Facinelli, Hazardous Materials Management Specialist

Location	Operations	Hazardous Wastes
Building #5	Laboratory- testing and research Old laboratory	General lab waste, flammable liquids, corrosives, sink waste, rags, debris, adhesive waste, Alodine waste
	Spray booth	Miscellaneous waste, spray booth waste, gun- wash, rags, wipers, etc.
	Hand-Line	Corrosive liquids, rinsewater, wastewater
	Oven-bake	ENERGY PRESENTATION
Building #12	Phone System	
Building #18	Empty Offices	
Building #14	Storage for old equipment and old spray booth no longer in use	
Building #15	Maintenance	Used oil, parts washer and miscellaneous wastes
	Masking application	Mary Mary Company
	Abrasive blasting	Excluded recyclable material
	Spray booth	Miscellaneous wastes, paint wastes, gun- wash, rags, booth filters
	Storage for old equipment	
Building #16	Gridlock	Coolant, cutting fluids, rags, miscellaneous wastes
	Spray booth	Paint wastes, booth filters, gun-wash, etc.
	Adhesive Operations	Adhesive wastes, Alodine wastes
Building #17	Repair	Miscellaneous wastes, gunwash, rags, solvent, debris, etc.
	Chromated conversion coating	Alodine waste
Building #19	Empty building	The designation of the second
Building #20	Prototype building	Miscellaneous wastes, rags, solvent, debris
Building #21	Empty- Temp. packaging and shipping	Management Agency Agency (Agency Agency
Building #22	Storage	BOOK SECTION OF PROPERTY
Building #24	FAA Repair	Miscellaneous wastes, rags, solvent, debris
	Chromated conversion coating	Alodine waste
	Flame spray booth, silicon spray application	Spray booth wastes, filters, gun-wash, adhesive wastes, etc.
	Spot application	Phosphoric acid waste, phosphoric acid rinse alodine rinse
Building #27	Utilities, boilers, compressors and chillers	Oily water, miscellaneous waste, rags, solvent, debris, descaling waste, used oil

- LABS - TESTING/RESEARCH

SPRAY BOOTH ?

-Modine waste bin BEHIND BUILDING - AGT WASTE " UNDERGROUND VAULT - SINGHOSTE, WASTEMATER, rinsewater, lab sinks at hand free waste - acids i bases HAND-LINE?

BUILDING #12

COMPOTER PHONE SYSTEM

Vanite hexane - Spen, uniqueled in sink underground weste line underground tank containing waste

- lab worde Allon me love of,

boots wester gon work atc.

-miscelianesus waste.

BUILDING #18 - EMPTY OFFICES

BUILDING #14

- STORAGE - OLD EQUIPMENT -OLD SPRAY BOOTH

WILDING #15

-MAINTENANCE

-MASKING APPLICATION

BLASTING

-SPRAY BOOTH

-STORAGE - OLD EQUIPMENT

used est, miscelionerus waste bin paret un gur wash, rags, booth filters, = pa rescirded tecyclobie material from blasting operations

WILDING #16 -GRIDLOCK SPRAY BOOTH ADHESIVE

rans etc. - coolen + /cutting fluids, miscellaneous mostes mant waste - booth - sinnesh Addition nestes - "Almerna was a fun

- REPAIR
- -PAINT BOOTH ?
- -CHROMATED CONVERSION COATING
- -3987-6800-6804

-misce augrus wastes

paint both mastes -gonnesh

Chromoum + water - "Alodine waste bin

BUILDING # 19 -EMPTY

BUILDING #20 - PROTOTYPE BUILDING

-miscenancous wastes
ray, solvent, debris

BUILDING # 21 EMPTY - TEMPORARY - PACKAGING & SHIPPING

301LDING # 22

· STORAGE

BUILDING #24

- -FAA REPAIR
- -CHROMATED CONVERSION COATING
- FLAME SPRAY BOOTH
- SILICON SPRAY/APPLICATION
- SPOT APPLICATION PHOSPHORIC ACID

PARTHADINESINE

- miscellaneous wastes - spray botto wastes - filters, etc. -chromium i mater - "Alodine" waste bin

phosphoric acid waste

gransh padhesive mastes

phosphoric acid ring

and other ringe

44LDING #25 ?

- UTILITIES

-BOILERS

- COMPRESSORS

- CHILLERS

only nater

transact miscellaneous waste

-describe unste

- usedoil

BUILDING#28

-GUARD OFFICES

UILDING # 31
PRODUCTION
HONEYCOMB CORE
ETHYLENE GLYCOL - APPLICATION
HEAT EXCHANGE MACHINING OF

standard
- Miscellaneous wastes
- metal shavings
- ctrylene glycol?

STORAGE RECEIVING

UILDING #32A & EMPTY

WILDING #32B PROZEN STORAGE

BUILDING #40

- HONEYCOMB FORMING

"print/solvent/spaldobris"
- Standard miscollanoms wastes
- monal shavings

BUILDING # 41

- EMPTY - OLD AUTOCLAVE

BUILDING #53 /AREA SURROUNDING

-OLD COGEN PLANT

- EMPTY BUILDINGS

- ON SITE WASTEWATER TREATMENT PLANT

COBEN VOID DE MIRELEN VOID DE COMENTANTE CARENT COORDE

BUILDING 27 Sontainment &

-MACHINE SHOP

tetandard miscellaneous waste

-UTILITIES

WILDING #58

- CMM INSPECTION

301LPING #59

- AUTOMOTIVE PAINT SHOP

- WELDING SHOP

- WOOD SHOP

- AUTO MAINTENANCE

- atandood miscellaneous waste IDA 10000

- used oil spen - unlabeled

- Standard master splay boots washer - Standard musce lement; washe

- HAZARDOUS WASTE PROCESSING & STORAGE Emything!

HAZARDOUS MATERIALS STORAGE

CONTRACT TOOL STORAGE WAXY-PROTECTIVE COATING

- oil water

-miscellaneous Handari

-STEAM CLEANING (BRAYCOTE REMOVAL FROM TOOLS)

adorground line?

BUILDING #304 + NEARBY AREA

-EXCLUDED RECYCLABLE MATERIAL

-NON-HAZARDOUS STORAGE

- GROUNDWATER TREATMENT SYSTEM -activated control waste &

- nun-linz dust. blasting - excluded ranglable

Next az Al Shaving from trimming cor Aloxide - Grit Blasting Operation

BUILDING #843

-RECORDS STORAGE

MISCELLANEOUS YARD STORAGE

-TOOL STORAGE

-EQUIPMENT STORAGE

-SALVAGE YARD

RIVERSIDE FLOOD CONTROL CHANNEL

- ON SITE RETENTION BASIN

GENERAL OFFICE/FACILITY

VCFT's labeled as non-nat instead of universal

CONSTRUCTION DECOMMISSIONING OF BUILDINGS

universal wast alkaline ba

aspectos.